

Struck Corporation
PO Box 307
Cedarburg, WI 53012

Phone: (262) 377-3300
Fax: (262) 377-9247
Email: parts@struckcorp.com

Abbreviated Parts list for MH4800, MH5000, MH6000, MH7000, MH8000, MH4900
Prices effective as of 8-01-18. Prices and availability subject to change without notice.

| Part # | Description | Price |
|-----------|--|----------|
| 001228 | Front Idler Assembly: (old # 209, Double check measurements on MH5000) <i>Includes: Bushings, Knurled washers, o-rings</i> | \$362.54 |
| 000210kit | Idler Wheel Assembly, 9-1/2": <i>Includes: O-Rings, bushings</i> | \$74.98 |
| 1218XX | Idler Wheel Assembly, 4 1/2":- Hardened (old # 211 was 4 in. Call factory w/ questions) <i>Includes: bushings</i> | \$71.26 |
| 001219 | Rear Drive Assembly: (old # 212, Double check measurements) on MH5000) <i>Includes: Bushings, knurled washers, o-rings</i> | \$392.54 |
| 000213kit | Axle, Idler Wheel <i>Includes: 1 axle, 1 snap ring, 1 spring pin, 15 washers, 1 grease zerck, 6 o-rings)</i> | \$36.21 |
| 000214kit | Axle, Rear Drive Kit <i>Includes: 1 snap ring, 15 washers, 1 grease zerck, 1 bolt with nut</i> | \$64.52 |
| 000215kit | Axle, Front Idler Sprocket Assembly <i>Includes: 2 snap rings, 10 washers</i> | \$52.79 |
| 000223 | Shaft | \$50.74 |
| 000231 | Axle support, (replaced by 001211, except on the MH6000) | \$14.92 |
| 000232sfp | Shim | \$1.31 |
| 000233 | Spring, Front Axle, Inside Yellow | \$37.69 |
| 000234 | Spring, Front Axle, Outside Black | \$42.23 |
| 000235sfp | Washer, 1-9/16 OD x 7/16 ID | \$0.84 |
| 000240 | O-Ring, 1-1/8 OD x 7/8 ID | \$0.26 |
| 000242 | Washer, 7/8" | \$0.45 |
| 000243kit | Bearing Assembly (includes 2 shells) | \$27.56 |
| 000252kit | Bearing Assembly (includes 2 shells) | \$12.24 |
| 000262sfp | Tube, Spring Stop | \$3.56 |
| 000429 | Throttle Cable Assembly | \$24.41 |
| 000436 | Shaft | \$29.50 |
| 000444 | Ignition Switch | \$19.70 |
| 000536A | Chain, Drive # 50 | \$21.38 |
| 000536B | Link, Master Connector # 50 | \$2.88 |
| 001090 | Chain, Drive # 80, 29 Pitches, (old # 537) | \$38.63 |
| 001091 | Link, Master Connector # 80, (old # 537B) | \$9.16 |
| 000616 | Breather/Filter | \$15.57 |
| 000680 | Hydraulic Filter Assembly | \$48.65 |
| 000680B | Filter Canister, Hydraulic - Napa No. 1259 | \$14.42 |
| 000455B | Filter Canister, Hydraulic (above serial # H1371) Napa 1203 | \$29.61 |
| 000715 | Disk Drive Assembly Complete | \$79.88 |
| 000724 | Primary Drive | \$127.46 |

| | | |
|-----------|---|---------------------|
| 002061 | Zerk (oil) Fitting for axle (oil gun) | \$0.55 |
| 001030sfp | Rod (old # 820) | \$18.75 |
| 001599kit | SET of Heavy Duty Tracks (551X Chain, replaces 925 & 1204 Call to check measurement on MH5000) | \$1,841.00 |
| TSO40 | SET of Track Shoes (Grouser) & Bolts | \$441.00 |
| TSO45P | SET of Non-Marking Shoes & Bolts | \$1,331.00 |
| 000999 | 2405002 Kohler Gas Fuel Filter (Struck # 535) | \$9.29 |
| 001101 | 2408305 Kohler Precleaner Element (foam) and 2408303 Kohler Air Cleaner Element (paper) | set only \$22.65 |
| 001103 | 1205001 Kohler Oil Filter | \$13.74 |
| 001365 | Air Cleaner (# 841497) Briggs-31, 35HP | \$31.85 |
| 001366 | Fuel Filter (# 691035) Briggs-31, 35 HP | \$8.44 |
| 001367 | Oil Filter (492932) Briggs-31, 35 HP | \$11.05 |
| 004005 | Disk Drive Assembly Complete (MH4900 & MH8000) | \$85.16 |
| 004006 | Primary Drive (MH4900 & MH8000) | \$175.28 |
| 004007 | # 60 Chain including connector link (MH4900 & MH8000) | \$19.95 |

Shipping and handling costs will be added to your order amount. We accept VISA, Mastercard, AMEX, Discover, PayPal and checks with a 2 week waiting period. Make checks payable to Struck Corp.